
Space Launch Delta 45 Hazard Area



SPACEX STARLINK 4-8

20 FEB 22

LAUNCH HAZARD AREA COORDINATES

(PURPLE BOX ON MAP)

28° 37'52 N 80° 36'50 W 28° 36'00 N 80° 21'00 W 27° 59'00 N 79° 12'00 W 27° 55'00 N 79° 15'00 W 28° 30'10 N 80° 32'53 W Please remain clear of the

Launch Hazard Area from:

7:15 AM - 12:15 PM

If launch is delayed the next attempt will be 21 FEB 22.

Backup Launch Hazard Area Times:

7:00 AM - 11:45 AM

Launch Information Recorded Line:

1-800-470-7232